

QUAKERTOWN COMMUNITY SCHOOL DISTRICT

CAPITAL IMPROVEMENTS PLAN 2019

Update Report on Findings and Recommendations

Prepared by:



QCSD - CAPITAL IMPROVEMENTS PLAN

EXECUTIVE SUMMARY

Presented herein is a report of the Quakertown Community School District (QCSD) Capital Improvements Plan dated October 2019.

In preparing this plan, a condition survey of the buildings was performed, and a list of facility needs compiled with additional input provided by QCSD's maintenance department and administrative staff. The items of work and costs noted in this report address the existing conditions only and do not include additions or renovations that would result from increased enrollment, program/curriculum revisions, etc.

D'Huy Engineering, Inc. would like to thank the QCSD for our continued relationship as your trusted advisor and working with us in preparing the Capital Improvements Study. We would also like to thank the QCSD Board of School Directors, Mr. Rob Christine, Mr. Zach Schoch, and the respective staff members for helping us with background information, and for guiding us through the facilities.

SUMMARY OF REPORT

The format of the report is as follows:

INTRODUCTORY SECTIONS:

- Tab 1 This section contains the Executive Summary.
- Tab 2 This section contains the logic matrix, priority index factors affecting priority ratings and a list of categories of work. This information was used in establishing the project priorities.

SECONDARY EDUCATIONAL FACILITY PROFILES:

- Tab 3 This section contains a brief summary of the building systems, observations and recommendations for the Quakertown Community High School.
- Tab 4 This section contains a brief summary of the building systems, observations and recommendations for the Strayer Middle School.
- Tab 5 This section contains a brief summary of the building systems, observations and recommendations for the Sixth Grade Center.

ELEMENTARY EDUCATIONAL FACILITY PROFILES:

Tab 6 This section contains a brief summary of the building systems, observations and recommendations for Pfaff Elementary School.

QCSD - CAPITAL IMPROVEMENTS PLAN

- Tab 7 This section contains a brief summary of the building systems, observations and recommendations for Quakertown Elementary School.
- Tab 8 This section contains a brief summary of the building systems, observations and recommendations for Richland Elementary School.
- Tab 9 This section contains a brief summary of the building systems, observations and recommendations for Trumbauersville Elementary School.

ANCILLARY FACILITY PROFILES:

- Tab 10 This section contains a brief summary of the building systems, observations and recommendations for the QCSD Stadium / Alumni Field.
- Tab 11 This section contains a brief summary of the building systems, observations and recommendations for the Facilities Building.

SUMMARY SECTIONS:

- Tab 12 This section contains recommendations itemized by priority order for each facility. It should be noted that even though each item of work could be addressed individually, it would be more cost effective and practical to combine items of work; e.g., ceiling tile/grid replacement, lighting replacement, HVAC replacement, etc.
- Tab 13 This section contains recommendations itemized by priority with all the facilities grouped together. It should be noted that even though each item of work could be addressed individually, it would be more cost effective and practical to combine items of work; e.g. ceiling tile/grid replacement, lighting replacement, HVAC replacement, etc.
- Tab 14 This section identifies the proposed capital projects for the next three years. Project selection, scope, and budget must be confirmed with QCSD.
- Tab 15 This section contains information regarding completed Capital Improvements projects since 2019.
- Tab 16 This section contains a Summary of Roof Systems and Warranty information.

MISCELLANEOUS INFORMATION:

- Tab 17 This section provides building code clarifications.
- Tab 18 Environmental Control Systems, Inc. AHERA 3-year inspection report dated March 1, 2018.

QCSD - CAPITAL IMPROVEMENTS PLAN

In general, this report does not include items that are considered regular maintenance items and does not include costs for new additions that may be required and are not recommended in the report. Items with an estimated cost below \$10,000 are not shown in the report unless they are part of a much larger project when aggregated. It is anticipated that projects with costs less than \$10,000 would be handled through annual repair and maintenance budgets. For example, a single area may cost less than \$10,000 to carpet; however, when there are an adequate number of areas to be carpeted in a single building, they may show up on the list.

A majority of the cost estimates for work recommendations listed for the schools were prepared from partial and/or schematic plans. The estimates were also calculated using the best available information at the time this report was written. Prior to budgeting or performing any work on any facility, a detailed material takeoff and review of scope should be performed by qualified personnel.

D'Huy Engineering, Inc. did not review/address environmental issues such as asbestos, radon, lead, etc. Some figures regarding asbestos remediation were, however, extrapolated from the District AHERA report regarding Asbestos Containing Material (ACM) present in each building. Prior to budgeting or performing any work in these areas, a detailed review of these items and other environmental issues should be thoroughly investigated.

This plan confirms the need for district-wide facility improvements. The review must, however, acknowledge that the District's facilities are well maintained and show that the pride of the QCSD is clearly evident. This plan should be updated annually based on the District's funds available and current needs. This will ensure that the QCSD's physical plant is well maintained to provide for educational needs.

It is the intent of D'Huy Engineering, Inc. that this plan serve as a working document for the District and, therefore, should not be considered a final statement that ends at this point. The priorities have been established using a logic matrix; however, the entries in the matrix are necessarily subjective. It is anticipated that these priorities may change after continued review by the Administration and Board. It is our hope that the District will continue to review and update the plan as funds become available for work to be performed. As work is completed and/or as additional items are identified in the future, the data can be updated to reflect a current situation at any time.

QUAKERTOWN COMMUNITY SCHOOL DISTRICT FACILITIES STUDY

PRIORITY INDEXING

Recommendations have been assigned a priority index which represents a degree of need. The priority indexing ranges from 2 to 10, with 10 representing the highest degree of need.

| 9, 10 | Critical – Should be addressed immediately |
|-------|---|
| 7, 8 | Serious – Should be addressed promptly |
| 5, 6 | Necessary – Should be budgeted for |
| 3, 4 | Suggested to improve operations |
| 2 | Not presently essential – Will likely need attention in the near future |
| 1 | Provide handicapped accessibility |
| 0 | Contingency, miscellaneous, and unidentified items including implementing asbestos assessment and management plan |

FACTORS AFFECTING PRIORITY RATINGS

- Age of specific plant facility components (including repairs and reconstruction).
- Use of specific plant facility components, e.g.:

Usage Priority
Not in use Low
Leased Medium
Occasional High
Regular Very High

Built-in redundancies, e.g.:

RedundancyPriority2 BoilersLow1 BoilerHigh

- Imminent danger/hazard to occupants from the existing condition of the plant component.
- Criticality of specific component in relation to functioning of overall facility, including consideration of effect on other plant components, e.g.:

ComponentPriorityRoofHighCurtainLow

- Present physical condition at time of survey
- Reported problems, including any repair history
- Deficiencies in identified plan component as it relates to its intended use.
- Educational impact of deterioration, deficiency, or existing condition of specific plant component.
- Life cycle evaluation of present recommendation on projected life of specific plan.
- Consideration of domino effect from failure of specific plan component.

CAPITAL IMPROVEMENTS PLAN

CATEGORIES OF WORK

| <u>CATEGORY</u> | DESCRIPTION |
|-----------------|--|
| AF | ATHLETIC FACILITIES |
| В | BOILER REPLACEMENT |
| CO | CONCRETE WORK |
| CA | CAULKING |
| CN | CONTINGENCY |
| CT | CEILING TILE |
| D | DOORS |
| ED | EXTERIOR DOORS |
| EL | IMPROVE EXTERIOR LIGHTING |
| EP | EXTERIOR PAINT |
| ES | UPGRADE ELECTRICAL SERVICE |
| EV | ELEVATOR |
| FA | FIRE ALARM/CAMERAS |
| FC | FLOOR CARPET |
| FT | FLOOR TILE |
| FTK | FUEL TANK |
| GL | GLASS REPLACEMENT |
| НА | PROVIDE HANDICAPPED ACCESSIBILITY |
| HV | HEATING, VENTILATION, AIR CONDITIONING, CONTROLS |
| IC | UPGRADE INTERCOM |
| ID | INTERIOR DOORS |
| IL | IMPROVE INTERIOR LIGHTING |
| IP | INTERIOR PAINT |
| L | LANDSCAPING |
| M | MASONRY |
| P | PLUMBING |
| PA | PAVING WORK |
| PK | ADDITIONAL PARKING |
| PS | PROPERTY SURVEYS |
| R | ROOF WORK |
| SC | STAGE REPAIRS |
| SL | STUDENT LOCKERS |
| SS | STORM SYSTEMS |
| TR | TOILET ROOMS |
| UN | UNCATEGORIZED |
| WR | WINDOW REPLACEMENT/REPAIR |
| WS | WINDOW SHADES, BLINDS, DRAPES |



Quakertown Community School District Logic Matrix for Assigning Priorities

| RATING | | | | PARAMETERS | | | |
|-----------------------|---|--|---|--|--|---------------------|----------------------|
| | SAFETY | EDUCATIONAL IMPACT | PHYSICAL CONDITIONS | DOMINO EFFECT | ECONOMIC IMPACT | AGE | LIFE EXPECTANCY |
| 5 | UNSAFE NEEDS IMMEDIATE ATTENTION | CRITICAL WILL CAUSE SCHOOL TO BE CLOSED | CRITICAL NEEDS IMMEDIATE ATTENTION | GREATLY IMPACTS OTHER ELEMENTS | IMMEDIATE ACTION SAVES MUCH LATER | OVER 20 YEARS | LESS THAN 5 YEARS |
| 4 | NOT UNSAFE BUT NEEDS IMMEDIATE ATTENTION | SERIOUS DISRUPTION | VERY POOR ADDRESS PROMPTLY | MODERATE IMPACT TO OTHER ELEMENTS | PROMPT ACTION SAVES MUCH LATER | 10 - 20 YEARS | 5 - 10 YEARS |
| 3 | NEEDS PROMPT ATTENTION | MODERATE DISRUPTION | POOR SHOULD BE BUDGETED | a a | PROMPT ACTION SAVES MODERATELY | 5 - 10 YEARS | 10 - 15 YEARS |
| 2 | SAFE BUT SHOULD BE BUDGETED | SLIGHT DISRUPTION | ACCEPTABLE COULD BE IMPROVED | SLIGHT IMPACT TO OTHER ELEMENTS | ACTION IN 3 YEARS SAVES MUCH | 3 - 5 YEARS | 15 - 20 YEARS |
| 1 | SAFE BUT WILL NEED WORK IN FUTURE | MINOR DISRUPTION TO SMALL GROUP | GOOD - WILL NEED WORK IN FUTURE | | LITTLE SAVINGS | 1 - 3 YEARS | 20 - 30 YEARS |
| 0 | NO SAFETY HAZARD | NO DISRUPTION | EXCELLENT | NO IMPACT ON OTHER ELEMENTS | NO SIGNIFICANT IMPACT | LESS THAN 1 YEAR | OVER 30 YEARS |
| IMPORTANCE FACTORS | 5 | 5 | 3 | 3 | 2 | | 1 |

PRIORITY = ((SAx5) + (EIx5) + (PCx3) + (DEx3) + (EIx2) + AG + LE)/10

MODIFIED DIVISOR IS 8 (FOR PRIORITY ADJUSTMENT)

| Building | item | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit (sf, LF, etc.) | Unit Cost | Estimated Cost Including 20% Indirect Costs | Area | Category |
|------------------------------|--|----|----|----|----|----|----|----|----------|----------|------------------------|---------------|---|-------------------|----------|
| Facilities Building | New emergency generator | 5 | 2 | 5 | 5 | 5 | 0 | 1 | 8 | 1 | LS | \$ 150,000.00 | \$ 180,000.00 | M/E/P | ES |
| Facilities Building | New fire alarm system | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 10,200 | SF | \$ 3.00 | \$ 36,720.00 | Interior | FA |
| Facilities Building | New Surveillance Camera System (8 cameras) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 8 | SF | \$ 3,600.00 | \$ 34,560.00 | Site | PA |
| Facilities Building | New heat system in shop and storage | 2 | 0 | 4 | 4 | 1 | 5 | 5 | 5 | 6,500 | SF | \$ 38.00 | \$ 296,400.00 | M/E/P | HV |
| Facilities Building | Windows replacement in shop | 2 | 0 | 3 | 2 | 1 | 5 | 5 | 4 | 500 | SF | \$ 70.00 | \$ 42,000.00 | Building Envelope | WR |
| Facilities Building | New entrance doors/transom/sidelights | 2 | 0 | 3 | 2 | 1 | 5 | 5 | 4 | 200 | SF | \$ 70.00 | \$ 16,800.00 | Building Envelope | ED |
| Facilities Building | Replace exterior man doors (2 single) | 2 | 0 | 3 | 2 | 1 | 5 | 5 | 4 | 2 | EA | \$ 3,500.00 | \$ 8,400.00 | Building Envelope | ED |
| Facilities Building | Replace existing gas & diesel pumps (dispensers) | 3 | 0 | 4 | 2 | 1 | 0 | 0 | 4 | 3 | EA | \$ 4,500.00 | \$ 16,200.00 | Site | FTK |
| Facilities Building | Fume hood/welding station | 3 | 0 | 4 | 2 | 1 | 0 | 0 | 4 | 1 | LS | \$ 20,000.00 | \$ 24,000.00 | M/E/P | HV |
| Facilities Building | New walk-in refrigerator/freezer | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | LS | \$ 80,000.00 | \$ 96,000.00 | Interior | UN |
| Facilities Building | Mill and overlay all lots and drives | 0 | 0 | 0 | 1 | 0 | 1 | 3 | 1 | 10,000 | SY | \$ 2.00 | \$ 24,000.00 | Site | PA |
| Facilities Building | Roof Replacement (20 year as of 2019) | 0 | 0 | 0 | 1 | 0 | 0 | 1 | 0 | 10,200 | SF | \$ 13.00 | \$ 159,120.00 | Site | PA |
| Field House/Athletic Site | Replace existing paving from ticket booths to visitor's side | 2 | 0 | 4 | 2 | 1 | 4 | 4 | 4 | 31,500 | SF | \$ 2.00 | \$ 75,600.00 | Site | PA |
| Field House/Athletic Site | Replace synthetic turf | 2 | 1 | 2 | 1 | 2 | 3 | 5 | 4 | 1 | EA | \$ 425,000.00 | \$ 510,000.00 | Site | ES |
| High School | Gymnasium indoor track resurfacing replacement | 2 | 1 | 3 | 2 | 4 | 4 | 5 | 5 | 10,000 | SF | \$ 20.00 | \$ 240,000.00 | Site | AF |
| High School | New operable bleacher replacement (upper Level) | 2 | 1 | 3 | 2 | 4 | 4 | 5 | 5 | 800 | EA | \$ 260.00 | \$ 249,600.00 | Site | AF |
| High School | New operable bleacher replacement (gym Floor) | 2 | 1 | 3 | 2 | 4 | 4 | 5 | 5 | 800 | EA | \$ 260.00 | \$ 249,600.00 | Site | AF |
| High School | Track resurfacing | 2 | 1 | 3 | 2 | 4 | 4 | 5 | 5 | 1 | LS | \$ 275,000.00 | \$ 330,000.00 | Site | AF |
| High School | Gym floor refinishing (by QCSD maintenance program) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Interior | AF |
| High School | Synthetic turf replacement | 2 | 1 | 1 | 1 | 2 | 3 | 4 | 3 | 1 | LS | \$ 425,000.00 | \$ 510,000.00 | Site | AF |
| High School | Repave all lots and drives (mill and overlay) | 0 | 0 | 1 | 2 | 0 | 2 | 2 | 1 | 328,750 | SF | \$ 2.00 | \$ 789,000.00 | Interior | PA |
| Pfaff ES | Geothermal pipe vault repairs | 4 | 3 | 4 | 5 | 3 | 4 | 5 | 8 | 1 | LS | \$ 85,000.00 | \$ 102,000.00 | M/E/P | HV |
| Pfaff ES | Exterior safety bollards allowance (By QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Site | UN |
| Pfaff ES | Paving replacement at bus drop-off | 3 | 2 | 5 | 4 | 2 | 4 | 5 | 7 | 13,500 | SF | \$ 5.00 | \$ 81,000.00 | Site | PA |
| Pfaff ES | Paving replacement at parent drop-off | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 66,600 | SF | \$ 2.00 | \$ 159,840.00 | Site | PA |



| | | | | | | | KAFI | | | | | | | | |
|----------|---|----|----|----|----|----|------|-----|----------|----------|------------------------|---------------|---|-------------------|----------|
| Building | ltem | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit (sf, LF, etc.) | Unit Cost | Estimated Cost Including 20% Indirect Costs | Area | Category |
| Pfaff ES | Sidewalk replacement at inlet | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 1 | LS | \$ 7,500.00 | \$ 9,000.00 | Site | со |
| Pfaff ES | New access control system | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 85,000 | SF | \$ 1.50 | \$ 153,000.00 | Interior | UN |
| Pfaff ES | New surveillance camera system (10 cameras) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 10 | SF | \$ 3,600.00 | \$ 43,200.00 | Interior | FA |
| Pfaff ES | Interior LED Lighting Upgrade/Occupancy Sensors / lighting controls | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 50,000 | SF | \$ 8.00 | \$ 480,000.00 | Interior | IL |
| Pfaff ES | Interior LED Lighting Gym and Cafeteria (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 35,000 | SF | \$ 4.00 | \$ 168,000.00 | Interior | IL |
| Pfaff ES | Exterior LED lighting (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 1 | LS | \$ 150,000.00 | \$ 180,000.00 | Site | EL |
| Pfaff ES | New ceiling tiles (during lighting upgrade) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 85,000 | SF | \$ 2.00 | \$ 204,000.00 | Interior | СТ |
| Pfaff ES | Gym floor refinishing (by QCSD maintenance program) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | LS - | \$ 15,000.00 | \$ 18,000.00 | Interior | AF |
| Pfaff ES | Window caulk joints | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 12,000 | LF | \$ 12.00 | \$ 172,800.00 | Building Envelope | CA |
| Pfaff ES | Brick control joints | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 7,500 | LF | \$ 12.00 | \$ 108,000.00 | Building Envelope | М |
| Pfaff ES | Prep and paint canopy structure | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 5,000 | SF | \$ 8.00 | \$ 48,000.00 | Site | EP |
| Pfaff ES | Brick repair and cleaning of school marquee | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1,500 | SF | \$ 45.00 | \$ 81,000.00 | Site | М |
| Pfaff ES | Rear patio at main entrance retaining wall repair | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 480 | SF | \$ 35.00 | \$ 20,160.00 | Site | М |
| Pfaff ES | Miscellaneous masonry repairs/replacement | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 300 | SF | \$ 50.00 | \$ 18,000.00 | Building Envelope | М |
| Pfaff ES | Bench replacement at entrance | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 4 | EA | \$ 2,500.00 | \$ 12,000.00 | Site | UN |
| Pfaff ES | Repoint brick wall cap | 0 | 1 | 3 | 2 | 2 | 4 | . 5 | 3 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Site | М |
| Pfaff ES | Repoint/repair curved brick site wall | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 25,000.00 | \$ 30,000.00 | Site | М |
| Pfaff ES | Poured concrete cap on library site wall | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 11,500.00 | \$ 13,800.00 | Site | со |
| Pfaff ES | Poured concrete cap on low site wall | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 5,500.00 | \$ 6,600.00 | Site | со |
| Pfaff ES | Loading dock wall repairs/repointing/cleaning | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 35,500.00 | \$ 42,600.00 | Site | М |
| Pfaff ES | Raise concrete at courtyard | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 22,500.00 | \$ 27,000.00 | Site | со |
| Pfaff ES | Repair retaining wall cap at courtyard | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 10,500.00 | \$ 12,600.00 | Site | М |
| Pfaff ES | Loading dock stair and railing replacement | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 35,000.00 | \$ 42,000.00 | Site | со |
| Pfaff ES | New stage curtains allowance (By QCSD) | 2 | 0 | 2 | 2 | 1 | 4 | 4 | 3 | 1 | EA | \$ 10,000.00 | \$ 12,000.00 | Interior | SC |
| Pfaff ES | Roof replacement | 0 | 1 | 2 | 2 | 2 | 4 | 5 | 3 | 40,000 | SF | \$ 22.00 | \$ 1,056,000.00 | Building Envelope | R |
| | | | | | | | | | | | | | | | |



| | | | | | | | IVAL I | | | | | | | | |
|--------------------|---|----|----|----|----|----|--------|----|----------|----------|------------------------|---------------|---|-------------------|----------|
| Building | ltem | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit (sf, LF, etc.) | Unit Cost | Estimated Cost Including 20% Indirect Costs | Area | Category |
| Quakertown ES | Exterior safety bollards allowance (by QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Site | UN |
| Quakertown ES | Total Building Renovation | | | | | | | | 0 | 41,172 | SF | \$ 300.00 | \$ 14,821,920.00 | Interior | R |
| Richland ES | Repave Bus Drop off loop | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 12,500 | SF | \$ 5.00 | \$ 75,000.00 | Site | PA |
| Richland ES | Sidewalk replacement | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 2,000 | SF | \$ 22.00 | \$ 52,800.00 | Site | со |
| Richland ES | Replace stair/handrail(s) | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 1 | EA | \$ 4,500.00 | \$ 5,400.00 | Site | НА |
| Richland ES | Exterior safety bollards allowance (By QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Site | UN |
| Richland ES | Pave all lots and drives | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 77,750 | SF | \$ 2.00 | \$ 186,600.00 | Site | PA |
| Richland ES | New access control system | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 43,390 | SF | \$ 2.00 | \$ 104,136.00 | Interior | UN |
| Richland ES | New surveillance camera system (10 Camera) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 10 | EA | \$ 3,600.00 | \$ 43,200.00 | Interior | FA |
| Richland ES | Secured vestibule pass-through windows | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 1 | LS | \$ 7,500.00 | \$ 9,000.00 | Interior | UN |
| Richland ES | Interior LED Lighting Upgrade/Occupancy Sensors / lighting controls | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 33,390 | SF | \$ 8.00 | \$ 320,544.00 | Interior | IL |
| Richland ES | Interior LED Lighting Gym and Cafeteria (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 10,000 | SF | \$ 4.00 | \$ 48,000.00 | Interior | IL |
| Richland ES | Exterior LED lighting (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 12 | EA | \$ 3,500.00 | \$ 50,400.00 | Site | EL |
| Richland ES | New ceiling tiles (during lighting upgrade) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 43,390 | SF | \$ 2.00 | \$ 104,136.00 | Interior | СТ |
| Richland ES | Gym floor refinishing (by QCSD maintenance program) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Interior | AF |
| Richland ES | Miscellaneous masonry repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1,000 | SF | \$ 25.00 | \$ 30,000.00 | Building Envelope | М |
| Richland ES | Miscellaneous metal panel repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Building Envelope | UN |
| Richland ES | Playground underdrain (allowance) | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 25,000.00 | \$ 30,000.00 | Site | SS |
| Richland ES | Playground equipment replacement (Allowance) | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | EA | \$ 130,000.00 | \$ 156,000.00 | Site | AF |
| Richland ES | New stage curtains allowance (By QCSD) | 2 | 0 | 2 | 2 | 1 | 4 | 4 | 3 | 1 | EA | \$ 10,000.00 | \$ 12,000.00 | Interior | SC |
| Richland ES | Roof replacement | 0 | 1 | 2 | 2 | 2 | 4 | 5 | 3 | 34,000 | SF | \$ 16.00 | \$ 652,800.00 | Building Envelope | R |
| Sixth Grade Center | Exterior safety bollards allowance (By QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Site | UN |
| Sixth Grade Center | New access control system | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 85,579 | SF | \$ 1.50 | \$ 154,042.20 | Interior | UN |
| Sixth Grade Center | New surveillance camera system (10 Camera) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 10 | EA | \$ 3,600.00 | \$ 43,200.00 | Interior | FA |
| Sixth Grade Center | Carpet replacement in computer lab Room 133 | 2 | 2 | 4 | 2 | 0 | 5 | 5 | 5 | 1,200 | SF | \$ 8.00 | \$ 11,520.00 | Interior | FC |
| | | | | | | | | | | | | | | | |



| Building | . Item | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit (sf, LF, etc.) | Unit Cost | Estimated Cost Including 20% Indirect Costs | Area | Category |
|--------------------|---|----|----|----|----|----|----|----|----------|----------|------------------------|---------------|---|-------------------|----------|
| Sixth Grade Center | Interior LED Lighting Upgrade/Occupancy Sensors / lighting controls | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 75,579 | SF | \$ 7.00 | \$ 634,863.60 | Interior | IL |
| Sixth Grade Center | Exterior LED lighting (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 15 | EA | \$ 3,500.00 | \$ 63,000.00 | Site | EL |
| Sixth Grade Center | Library carpet replacement (Floor slab investigation/remediation) | 1 | 2 | 4 | 2 | 0 | 4 | 3 | 4 | 4,400 | SF | \$ 8.00 | \$ 42,240.00 | Interior | FC |
| Sixth Grade Center | New gymnasium sound system | 2 | 3 | 3 | 2 | 0 | 0 | 0 | 4 | 1 | LS | \$ 25,000.00 | \$ 30,000.00 | Interior | IC |
| Sixth Grade Center | 500+ locker replacement | 0 | 3 | 3 | 2 | 0 | 4 | 5 | 4 | 500 | EA | \$ 475.00 | \$ 285,000.00 | Interior | SL |
| Sixth Grade Center | Art room modification/new kiln (allowance) | 0 | 3 | 3 | 2 | 0 | 4 | 5 | 4 | 1 | LS | \$ 40,000.00 | \$ 48,000.00 | Interior | HV |
| Sixth Grade Center | New ceiling tiles (during lighting upgrade) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 85,579 | SF | \$ 3.00 | \$ 308,084.40 | Interior | СТ |
| Sixth Grade Center | Gym floor refinishing (by QCSD maintenance program) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Interior | AF |
| Sixth Grade Center | Façade masonry cleaning | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 2,500 | SF | \$ 1.00 | \$ 3,000.00 | Building Envelope | М |
| Sixth Grade Center | Mechanical screen wall masonry repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1,000 | SF | \$ 20.00 | \$ 24,000.00 | Building Envelope | М |
| Sixth Grade Center | Loading dock repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 25,000.00 | \$ 30,000.00 | Site | UN |
| Sixth Grade Center | Repave all lots and drives (mill and overlay) | 0 | 0 | 1 | 2 | 0 | 2 | 2 | 1 | 117,000 | SF | \$ 2.00 | \$ 280,800.00 | Site | PA |
| Strayer MS | Refinish/Replace existing stage floor and nosing | 5 | 2 | 5 | 4 | 3 | 4 | 5 | 8 | 2,500 | SF | \$ 4.00 | \$ 12,000.00 | Interior | sc |
| Strayer MS | Replace dust collection system (allowance) | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 1 | EA | \$ 30,000.00 | \$ 36,000.00 | Interior | HV |
| Strayer MS | Replace dust collector suppression systems (allowance) | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 1 | EA | \$ 25,000.00 | \$ 30,000.00 | Interior | HV |
| Strayer MS | Exterior safety bollards allowance (By QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 12 | EA | \$ 3,500.00 | \$ 50,400.00 | Site | UN |
| Strayer MS | Mill and overlay all lots and drives | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 231,500 | SF | \$ 2.00 | \$ 555,600.00 | Site | PA |
| Strayer MS | Sidewalk replacement | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 2,000 | SF | \$ 20.00 | \$ 48,000.00 | Site | со |
| Strayer MS | Inlet repairs | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 6 | EA | \$ 4,500.00 | \$ 32,400.00 | Site- | SS |
| Strayer MS | New access control system | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 190,000 | SF | \$ 1.50 | \$ 342,000.00 | Interior | UN |
| Strayer MS | New surveillance camera system (10 Camera) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 10 | EA | \$ 3,600.00 | \$ 43,200.00 | Interior | FA |
| Strayer MS | Secured vestibule pass-through windows | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 1 | LS | \$ 5,500.00 | \$ 6,600.00 | Interior | UN |
| Strayer MS | AC unit replacement in boys/girls locker rooms | 2 | 2 | 3 | 4 | 1 | 4 | 5 | 5 | 1 | EA | \$ 110,000.00 | \$ 132,000.00 | M/E/P | HV |
| Strayer MS | Interior LED Lighting Upgrade/Occupancy Sensors / lighting controls | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 175,000 | SF | \$ 8.00 | \$ 1,680,000.00 | Interior | IL |
| Strayer MS | Interior LED Lighting Gym and Cafeteria (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 15,000 | SF | \$ 4.00 | \$ 72,000.00 | Interior | IL |



| | | | | | | | KAFI | | | | | | | | |
|--------------------|---|----|----|----|----|----|------|----|----------|----------|------------------------|---------------|---|-------------------|----------|
| Building | ltem | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit (sf, LF, etc.) | Unit Cost | Estimated Cost Including 20% Indirect Costs | Area | Category |
| Strayer MS | Exterior LED lighting (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 25 | EA | \$ 1,000.00 | \$ 30,000.00 | Site | EL |
| Strayer MS | New bleachers - 200 seats (3 tier) | 2 | 2 | 3 | 3 | 0 | 3 | 3 | 4 | 200 | EA | \$ 250.00 | \$ 60,000.00 | Site | AF |
| Strayer MS | New track and football field - include fencing (allowance) | 2 | 2 | 3 | 3 | 0 | 3 | 3 | 4 | 1 | LS | \$ 600,000.00 | \$ 720,000.00 | Site | AF |
| Strayer MS | Replace wood split-rail fence | 3 | 0 | 5 | 1 | 0 | 4 | 5 | 4 | 300 | LF | \$ 40.00 | \$ 14,400.00 | Site | UN |
| Strayer MS | Rebuild baseball field and fencing | 2 | 1 | 3 | 3 | 0 | 4 | 4 | 4 | 1 | LS | \$ 310,000.00 | \$ 372,000.00 | Site | AF |
| Strayer MS | New ceiling tiles (during lighting upgrade) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 190,000 | SF | \$ 2.00 | \$ 456,000.00 | Interior | СТ |
| Strayer MS | Façade masonry cleaning | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 64,800 | SF | \$ 0.50 | \$ 38,880.00 | Building Envelope | М |
| Strayer MS | Miscellaneous masonry repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1,000 | SF | \$ 25.00 | \$ 30,000.00 | Building Envelope | М |
| Strayer MS | Repoint loading dock retaining wall | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1,000 | SF | \$ 25.00 | \$ 30,000.00 | Site | UN |
| Strayer MS | Paint exterior hollow metal doors and frames | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 15 | EA | \$ 500.00 | \$ 9,000.00 | Building Envelope | ED |
| Strayer MS | Roof replacement . | 0 | 1 | 2 | 2 | 2 | 4 | 3 | 3 | 152,000 | SF | \$ 22.00 | \$ 4,012,800.00 | Building Envelope | R |
| Strayer MS | Install storage building 32 x 60 (allowance) | 0 | 1 | 3 | 4 | 1 | 0 | 0 | 3 | 1 | LS | \$ 75,000.00 | \$ 90,000.00 | Site | UN |
| Trumbauersville ES | Repave Bus Drop off loop | 5 | 2 | 5 | 4 | 3 | 4 | 5 | 8 | 13,500 | SF | \$ 5.00 | \$ 81,000.00 | Site | PA |
| Trumbauersville ES | Interior LED Lighting Gym and Cafeteria (by QCSD) | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 15,000 | SF | \$ 4.00 | \$ 72,000.00 | Interior | IL |
| Trumbauersville ES | Secured vestibule | 4 | 2 | 5 | 4 | 2 | 4 | 5 | 7 | 1 | EA | \$ 25,000.00 | \$ 30,000.00 | Interior | UN |
| Trumbauersville ES | Exterior safety bollards allowance (By QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Site | UN |
| Trumbauersville ES | New access control system | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 54,647 | SF | \$ 1.50 | \$ 98,364.60 | Interior | UN |
| Trumbauersville ES | New surveillance camera system (10 Camera) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 40 | EA | \$ 3,600.00 | \$ 172,800.00 | Interior | FA |
| Trumbauersville ES | Sidewalk replacement | 3 | 1 | 3 | 4 | 3 | 3 | 4 | 5 | 1,500 | SF | \$ 20.00 | \$ 36,000.00 | Site | со |
| Trumbauersville ES | Interior LED Lighting Upgrade/Occupancy Sensors / lighting controls | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 39,647 | SF | \$ 8.00 | \$ 380,611.20 | Interior | IL |
| Trumbauersville ES | Exterior LED lighting (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 16 | EA | \$ 3,500.00 | \$ 67,200.00 | Site | EL |
| Trumbauersville ES | Loading dock guardrail replacement | 2 | 1 | 3 | 2 | 2 | 4 | 5 | 4 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Site | UN |
| Trumbauersville ES | New ceiling tiles (during lighting upgrade) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 54,647 | SF | \$ 2.00 | \$ 131,152.80 | Interior | СТ |
| Trumbauersville ES | Gym floor refinishing (by QCSD maintenance program) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | EA | \$ 15,000.00 | \$ 18,000.00 | Interior | AF |
| Trumbauersville ES | Façade masonry cleaning | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 35,000 | SF | \$ 0.50 | \$ 21,000.00 | Building Envelope | EP |
| | | | | | | | | | | | | | | | |



| Building | ltem | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit (sf, LF, etc.) | Unit Cost | Estimated Cost Including 20% Indirect Costs | Area | Category |
|--------------------|---|----|----|----|----|----|----|----|----------|----------|------------------------|--------------|---|-------------------|----------|
| Trumbauersville ES | Loading dock retaining wall repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 500 | SF | \$ 35.00 | \$ 21,000.00 | Site | М |
| Trumbauersville ES | Replacement of exterior doors (allowance) | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Building Envelope | ED |
| Trumbauersville ES | Loading dock repair / dock bumper | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 7,000.00 | \$ 8,400.00 | Site | М |
| Trumbauersville ES | Flat roof replacement (2 areas) | 0 | 1 | 2 | 2 | 2 | 4 | 3 | 3 | 3,500 | SF | \$ 22.00 | \$ 92,400.00 | Building Envelope | R |
| Trumbauersville ES | Repave all lots and drives (mill and overlay) | 0 | 0 | 1 | 2 | 0 | 2 | 2 | 1 | 66,600 | SF | \$ 2.00 | \$ 159,840.00 | Site | PA |
| | | | | | | | | | | | | Grand Total: | \$ 36,400,534.80 | | |



| Building | ltem | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit (sf, LF, etc.) | Unit Cost | Estimated Cost Including 20% Indirect Costs | Area | Category |
|---------------------|--|----|----|----|----|-----|----|----|----------|----------|------------------------|---------------|---|----------|----------|
| Facilities Building | New emergency generator | 5 | 2 | 5 | 5 | 5 | 0 | 1 | 8 | 1 | LS | \$ 150,000.00 | \$ 180,000.00 | M/E/P | ES |
| Facilities Building | New fire alarm system | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 10,200 | SF | \$ 3.00 | \$ 36,720.00 | Interior | FA |
| Pfaff ES | Geothermal pipe vault repairs | 4 | 3 | 4 | 5 | 3 | 4 | 5 | 8 | 1 | LS | \$ 85,000.00 | \$ 102,000.00 | M/E/P | HV |
| Richland ES | Repave Bus Drop off loop | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 12,500 | SF | \$ 5.00 | \$ 75,000.00 | Site | PA |
| Richland ES | Sidewalk replacement | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 2,000 | SF | \$ 22.00 | \$ 52,800.00 | Site | со |
| Richland ES | Replace stair/handrail(s) | 5 | 2 | 5 | 4 | . 2 | 4 | 5 | 8 | 1 | EA | \$ 4,500.00 | \$ 5,400.00 | Site | НА |
| Strayer MS | Refinish/Replace existing stage floor and nosing | 5 | 2 | 5 | 4 | 3 | 4 | 5 | 8 | 2,500 | SF | \$ 4.00 | \$ 12,000.00 | Interior | SC |
| Strayer MS | Replace dust collection system (allowance) | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 1 | EA | \$ 30,000.00 | \$ 36,000.00 | Interior | HV |
| Strayer MS | Replace dust collector suppression systems (allowance) | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 1 | EA | \$ 25,000.00 | \$ 30,000.00 | Interior | HV |
| Trumbauersville ES | Repave Bus Drop off loop | 5 | 2 | 5 | 4 | 3 | 4 | 5 | 8 | 13,500 | SF | \$ 5.00 | \$ 81,000.00 | Site | PA |
| Trumbauersville ES | Interior LED Lighting Gym and Cafeteria (by QCSD) | 5 | 2 | 5 | 4 | 2 | 4 | 5 | 8 | 15,000 | SF | \$ 4.00 | \$ 72,000.00 | Interior | IL |
| Pfaff ES | Exterior safety bollards allowance (By QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Site | UN |
| Pfaff ES | Paving replacement at bus drop-off | 3 | 2 | 5 | 4 | 2 | 4 | 5 | 7 | 13,500 | SF | \$ 5.00 | \$ 81,000.00 | Site | PA |
| Quakertown ES | Exterior safety bollards allowance (by QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Site | UN |
| Richland ES | Exterior safety bollards allowance (By QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Site | UN |
| Sixth Grade Center | Exterior safety bollards allowance (By QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Site | UN |
| Strayer MS | Exterior safety bollards allowance (By QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 12 | EA | \$ 3,500.00 | \$ 50,400.00 | Site | UN |
| Trumbauersville ES | Secured vestibule | 4 | 2 | 5 | 4 | 2 | 4 | 5 | 7 | 1 | EA | \$ 25,000.00 | \$ 30,000.00 | Interior | UN |
| Trumbauersville ES | Exterior safety bollards allowance (By QCSD) | 5 | 0 | 5 | 5 | 5 | 0 | 3 | 7 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Site | UN |
| Facilities Building | New Surveillance Camera System (8 cameras) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 8 | SF | \$ 3,600.00 | \$ 34,560.00 | Site | PA |
| Pfaff ES | Paving replacement at parent drop-off | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 66,600 | SF | \$ 2.00 | \$ 159,840.00 | Site | PA |
| Pfaff ES | Sidewalk replacement at inlet | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 1 | LS | \$ 7,500.00 | \$ 9,000.00 | Site | со |
| Pfaff ES | New access control system | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 85,000 | SF | \$ 1.50 | \$ 153,000.00 | Interior | UN |
| Pfaff ES | New surveillance camera system (10 cameras) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 10 | SF | \$ 3,600.00 | \$ 43,200.00 | Interior | FA |
| Richland ES | Pave all lots and drives | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 77,750 | SF | \$ 2.00 | \$ 186,600.00 | Site | PA |



13-1 Page 1 of 6

DRAFT

| Building | Item | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit | Unit Cost | Estimated Cost Including | Area | Category |
|---------------------|---|----|----|----|----|----|----|----|----------|----------|----------------|---------------|--------------------------|----------|----------|
| | | | | | | | | | | | (sf, LF, etc.) | | 20% Indirect Costs | | |
| Richland ES | New access control system | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 43,390 | SF | \$ 2.00 | \$ 104,136.00 | Interior | UN |
| Richland ES | New surveillance camera system (10 Camera) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 10 | EA | \$ 3,600.00 | \$ 43,200.00 | Interior | FA |
| Richland ES | Secured vestibule pass-through windows | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 1 | LS | \$ 7,500.00 | \$ 9,000.00 | Interior | UN |
| Sixth Grade Center | New access control system | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 85,579 | SF | \$ 1.50 | \$ 154,042.20 | Interior | UN |
| Sixth Grade Center | New surveillance camera system (10 Camera) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 10 | EA | \$ 3,600.00 | \$ 43,200.00 | Interior | FA |
| Strayer MS | Mill and overlay all lots and drives | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 231,500 | SF | \$ 2.00 | \$ 555,600.00 | Site | PA |
| Strayer MS | Sidewalk replacement | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 2,000 | SF | \$ 20.00 | \$ 48,000.00 | Site | со |
| Strayer MS | Inlet repairs | 4 | 1 | 4 | 4 | 3 | 4 | 5 | 6 | 6 | EA | \$ 4,500.00 | \$ 32,400.00 | Site | SS |
| Strayer MS | New access control system | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 190,000 | SF | \$ 1.50 | \$ 342,000.00 | Interior | UN |
| Strayer MS | New surveillance camera system (10 Camera) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 10 | EA | \$ 3,600.00 | \$ 43,200.00 | Interior | FA |
| Strayer MS | Secured vestibule pass-through windows | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 1 | LS | \$ 5,500.00 | \$ 6,600.00 | Interior | UN |
| Trumbauersville ES | New access control system | 3 | 0 | 5 | 5 | 5 | 0 | 3 | . 6 | 54,647 | SF | \$ 1.50 | \$ 98,364.60 | Interior | UN |
| Trumbauersville ES | New surveillance camera system (10 Camera) | 3 | 0 | 5 | 5 | 5 | 0 | 3 | 6 | 40 | EA | \$ 3,600.00 | \$ 172,800.00 | Interior | FA |
| Facilities Building | New heat system in shop and storage | 2 | 0 | 4 | 4 | 1 | 5 | 5 | 5 | 6,500 | SF | \$ 38.00 | \$ 296,400.00 | M/E/P | HV |
| High School | Gymnasium indoor track resurfacing replacement | 2 | 1 | 3 | 2 | 4 | 4 | 5 | 5 | 10,000 | SF | \$ 20.00 | \$ 240,000.00 | Site | AF |
| High School | New operable bleacher replacement (upper Level) | 2 | 1 | 3 | 2 | 4 | 4 | 5 | 5 | 800 | EA | \$ 260.00 | \$ 249,600.00 | Site | AF |
| High School | New operable bleacher replacement (gym Floor) | 2 | 1 | 3 | 2 | 4 | 4 | 5 | 5 | 800 | EA | \$ 260.00 | \$ 249,600.00 | Site | AF |
| High School | Track resurfacing | 2 | 1 | 3 | 2 | 4 | 4 | 5 | 5 | 1 | LS | \$ 275,000.00 | \$ 330,000.00 | Site | AF |
| Pfaff ES | Interior LED Lighting Upgrade/Occupancy Sensors / lighting controls | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 50,000 | SF | \$ 8.00 | \$ 480,000.00 | Interior | IL |
| Pfaff ES | Interior LED Lighting Gym and Cafeteria (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 35,000 | SF | \$ 4.00 | \$ 168,000.00 | Interior | IL |
| Pfaff ES | Exterior LED lighting (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 1 | LS | \$ 150,000.00 | \$ 180,000.00 | Site | EL |
| Richland ES | Interior LED Lighting Upgrade/Occupancy Sensors / lighting controls | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 33,390 | SF | \$ 8.00 | \$ 320,544.00 | Interior | IL |
| Richland ES | Interior LED Lighting Gym and Cafeteria (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 10,000 | SF | \$ 4.00 | \$ 48,000.00 | Interior | IL |
| Richland ES | Exterior LED lighting (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 12 | EA | \$ 3,500.00 | \$ 50,400.00 | Site | EL |
| Sixth Grade Center | Carpet replacement in computer lab Room 133 | 2 | 2 | 4 | 2 | 0 | 5 | 5 | 5 | 1,200 | SF | \$ 8.00 | \$ 11,520.00 | Interior | FC |
| | | | | | | | | | | | | | | | |



13-2 Page 2 of 6

| Building | Item | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit (sf, LF, etc.) | Unit Cost | Estimated Cost Including 20% Indirect Costs | Area | Category |
|------------------------------|---|----|----|----|----|----|----|----|----------|----------|------------------------|---------------|---|-------------------|----------|
| Sixth Grade Center | Interior LED Lighting Upgrade/Occupancy Sensors / lighting controls | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 75,579 | SF | \$ 7.00 | \$ 634,863.60 | Interior | IL |
| Sixth Grade Center | Exterior LED lighting (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 15 | EA | \$ 3,500.00 | \$ 63,000.00 | Site | EL |
| Strayer MS | AC unit replacement in boys/girls locker rooms | 2 | 2 | 3 | 4 | 1 | 4 | 5 | 5 | 1 | EA | \$ 110,000.00 | \$ 132,000.00 | M/E/P | HV |
| Strayer MS | Interior LED Lighting Upgrade/Occupancy Sensors / lighting controls | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 175,000 | SF | \$ 8.00 | \$ 1,680,000.00 | Interior | IL |
| Strayer MS | Interior LED Lighting Gym and Cafeteria (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 15,000 | SF | \$ 4.00 | \$ 72,000.00 | Interior | IL |
| Strayer MS | Exterior LED lighting (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 25 | EA | \$ 1,000.00 | \$ 30,000.00 | Site | EL |
| Trumbauersville ES | Sidewalk replacement | 3 | 1 | 3 | 4 | 3 | 3 | 4 | 5 | 1,500 | SF | \$ 20.00 | \$ 36,000.00 | Site | со |
| Trumbauersville ES | Interior LED Lighting Upgrade/Occupancy Sensors / lighting controls | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 39,647 | SF | \$ 8.00 | \$ 380,611.20 | Interior | IL |
| Trumbauersville ES | Exterior LED lighting (by QCSD) | 1 | 2 | 2 | 4 | 2 | 4 | 5 | 5 | 16 | EA | \$ 3,500.00 | \$ 67,200.00 | Site | EL |
| Facilities Building | Windows replacement in shop | 2 | 0 | 3 | 2 | 1 | 5 | 5 | 4 | 500 | SF | \$ 70.00 | \$ 42,000.00 | Building Envelope | WR |
| Facilities Building | New entrance doors/transom/sidelights | 2 | 0 | 3 | 2 | 1 | 5 | 5 | 4 | 200 | SF | \$ 70.00 | \$ 16,800.00 | Building Envelope | ED |
| Facilities Building | Replace exterior man doors (2 single) | 2 | 0 | 3 | 2 | 1 | 5 | 5 | 4 | 2 | EA | \$ 3,500.00 | \$ 8,400.00 | Building Envelope | ED |
| Facilities Building | Replace existing gas & diesel pumps (dispensers) | 3 | 0 | 4 | 2 | 1 | 0 | 0 | 4 | 3 | EA | \$ 4,500.00 | \$ 16,200.00 | Site | FTK |
| Facilities Building | Fume hood/welding station | 3 | 0 | 4 | 2 | 1 | 0 | 0 | 4 | 1 | LS | \$ 20,000.00 | \$ 24,000.00 | M/E/P | HV |
| Field House/Athletic Site | Replace existing paving from ticket booths to visitor's side | 2 | 0 | 4 | 2 | 1 | 4 | 4 | 4 | 31,500 | SF | \$ 2.00 | \$ 75,600.00 | Site | PA |
| Field House/Athletic Site | Replace synthetic turf | 2 | 1 | 2 | 1 | 2 | 3 | 5 | 4 | 1 | EA | \$ 425,000.00 | \$ 510,000.00 | Site | ES |
| Sixth Grade Center | Library carpet replacement (Floor slab investigation/remediation) | 1 | 2 | 4 | 2 | 0 | 4 | 3 | 4 | 4,400 | SF | \$ 8.00 | \$ 42,240.00 | Interior | FC |
| Sixth Grade Center | New gymnasium sound system | 2 | 3 | 3 | 2 | 0 | 0 | 0 | 4 | 1 | LS | \$ 25,000.00 | \$ 30,000.00 | Interior | IC |
| Sixth Grade Center | 500+ locker replacement | 0 | 3 | 3 | 2 | 0 | 4 | 5 | 4 | 500 | EA | \$ 475.00 | \$ 285,000.00 | Interior | SL |
| Sixth Grade Center | Art room modification/new kiln (allowance) | 0 | 3 | 3 | 2 | 0 | 4 | 5 | 4 | 1 | LS | \$ 40,000.00 | \$ 48,000.00 | Interior | HV |
| Strayer MS | New bleachers - 200 seats (3 tier) | 2 | 2 | 3 | 3 | 0 | 3 | 3 | 4 | 200 | EA | \$ 250.00 | \$ 60,000.00 | Site | AF |
| Strayer MS | New track and football field - include fencing (allowance) | 2 | 2 | 3 | 3 | 0 | 3 | 3 | 4 | 1 | LS | \$ 600,000.00 | \$ 720,000.00 | Site | AF |
| Strayer MS | Replace wood split-rail fence | 3 | 0 | 5 | 1 | 0 | 4 | 5 | 4 | 300 | LF | \$ 40.00 | \$ 14,400.00 | Site | UN |
| Strayer MS | Rebuild baseball field and fencing | 2 | 1 | 3 | 3 | 0 | 4 | 4 | 4 | 1 | LS | \$ 310,000.00 | \$ 372,000.00 | Site | AF |
| Trumbauersville ES | Loading dock guardrail replacement | 2 | 1 | 3 | 2 | 2 | 4 | 5 | 4 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Site | UN |



13-3 Page 3 of 6

DRAFT

| | | 2700.1 | | | | | | | | | | | | | |
|---------------------|---|--------|----|----|----|----|----|----|----------|----------|------------------------|---------------|---|-------------------|----------|
| Building | ltem | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit (sf, LF, etc.) | Unit Cost | Estimated Cost Including 20% Indirect Costs | Area | Category |
| Facilities Building | New walk-in refrigerator/freezer | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | LS | \$ 80,000.00 | \$ 96,000.00 | Interior | UN |
| High School | Gym floor refinishing (by QCSD maintenance program) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Interior | AF |
| High School | Synthetic turf replacement | 2 | 1 | 1 | 1 | 2 | 3 | 4 | 3 | 1 | LS | \$ 425,000.00 | \$ 510,000.00 | Site | AF |
| Pfaff ES | New ceiling tiles (during lighting upgrade) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 85,000 | SF | \$ 2.00 | \$ 204,000.00 | Interior | СТ |
| Pfaff ES | Gym floor refinishing (by QCSD maintenance program) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Interior | AF |
| Pfaff ES | Window caulk joints | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 12,000 | LF | \$ 12.00 | \$ 172,800.00 | Building Envelope | CA |
| Pfaff ES | Brick control joints | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 7,500 | LF | \$ 12.00 | \$ 108,000.00 | Building Envelope | М |
| Pfaff ES | Prep and paint canopy structure | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 5,000 | SF | \$ 8.00 | \$ 48,000.00 | Site | EP |
| Pfaff ES | Brick repair and cleaning of school marquee | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1,500 | SF | \$ 45.00 | \$ 81,000.00 | Site | М |
| Pfaff ES | Rear patio at main entrance retaining wall repair | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 480 | SF | \$ 35.00 | \$ 20,160.00 | Site | М |
| Pfaff ES | Miscellaneous masonry repairs/replacement | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 300 | SF | \$ 50.00 | \$ 18,000.00 | Building Envelope | М |
| Pfaff ES | Bench replacement at entrance | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 4 | EA | \$ 2,500.00 | \$ 12,000.00 | Site | UN |
| Pfaff ES | Repoint brick wall cap | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Site | М |
| Pfaff ES | Repoint/repair curved brick site wall | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 25,000.00 | \$ 30,000.00 | Site | М |
| Pfaff ES | Poured concrete cap on library site wall | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 11,500.00 | \$ 13,800.00 | Site | со |
| Pfaff ES | Poured concrete cap on low site wall | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 5,500.00 | \$ 6,600.00 | Site | со |
| Pfaff ES | Loading dock wall repairs/repointing/cleaning | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 35,500.00 | \$ 42,600.00 | Site | М |
| Pfaff ES | Raise concrete at courtyard | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 22,500.00 | \$ 27,000.00 | Site | со |
| Pfaff ES | Repair retaining wall cap at courtyard | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 10,500.00 | \$ 12,600.00 | Site | М |
| Pfaff ES | Loading dock stair and railing replacement | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 35,000.00 | \$ 42,000.00 | Site | со |
| Pfaff ES | New stage curtains allowance (By QCSD) | 2 | 0 | 2 | 2 | 1 | 4 | 4 | 3 | 1 | EA | \$ 10,000.00 | \$ 12,000.00 | Interior | SC |
| Pfaff ES | Roof replacement | 0 | 1 | 2 | 2 | 2 | 4 | 5 | . 3 | 40,000 | SF | \$ 22.00 | \$ 1,056,000.00 | Building Envelope | R |
| Richland ES | New ceiling tiles (during lighting upgrade) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 43,390 | SF | \$ 2.00 | \$ 104,136.00 | Interior | СТ |
| Richland ES | Gym floor refinishing (by QCSD maintenance program) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Interior | AF |
| Richland ES | Miscellaneous masonry repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1,000 | SF | \$ 25.00 | \$ 30,000.00 | Building Envelope | М |
| | I | | | | | | | | | | | | | | |



13-4 Page 4 of 6

| _ | _ | - | | _ |
|--------------------|---|---|---|---|
| n | R | Δ | F | Г |
| $\boldsymbol{\nu}$ | | _ | | |

| Building | ltem | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit (sf, LF, etc.) | Unit Cost | Estimated Cost Including 20% Indirect Costs | Area | Category |
|---------------------|---|----|----|----|----|----|----|----|----------|----------|------------------------|---------------|---|-------------------|----------|
| Richland ES | Miscellaneous metal panel repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Building Envelope | UN |
| Richland ES | Playground underdrain (allowance) | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 25,000.00 | \$ 30,000.00 | Site | SS |
| Richland ES | Playground equipment replacement (Allowance) | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | EA | \$ 130,000.00 | \$ 156,000.00 | Site | AF |
| Richland ES | New stage curtains allowance (By QCSD) | 2 | 0 | 2 | 2 | 1 | 4 | 4 | 3 | 1 | EA | \$ 10,000.00 | \$ 12,000.00 | Interior | SC |
| Richland ES | Roof replacement | 0 | 1 | 2 | 2 | 2 | 4 | 5 | 3 | 34,000 | SF | \$ 16.00 | \$ 652,800.00 | Building Envelope | R |
| Sixth Grade Center | New ceiling tiles (during lighting upgrade) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 85,579 | SF | \$ 3.00 | \$ 308,084.40 | Interior | СТ |
| Sixth Grade Center | Gym floor refinishing (by QCSD maintenance program) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | LS | \$ 15,000.00 | \$ 18,000.00 | Interior | AF |
| Sixth Grade Center | Façade masonry cleaning | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 2,500 | SF | \$ 1.00 | \$ 3,000.00 | Building Envelope | М |
| Sixth Grade Center | Mechanical screen wall masonry repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1,000 | SF | \$ 20.00 | \$ 24,000.00 | Building Envelope | М |
| Sixth Grade Center | Loading dock repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 25,000.00 | \$ 30,000.00 | Site | UN |
| Strayer MS | New ceiling tiles (during lighting upgrade) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 190,000 | SF | \$ 2.00 | \$ 456,000.00 | Interior | СТ |
| Strayer MS | Façade masonry cleaning | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 64,800 | SF | \$ 0.50 | \$ 38,880.00 | Building Envelope | М |
| Strayer MS | Miscellaneous masonry repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1,000 | SF | \$ 25.00 | \$ 30,000.00 | Building Envelope | М |
| Strayer MS | Repoint loading dock retaining wall | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1,000 | SF | \$ 25.00 | \$ 30,000.00 | Site | UN |
| Strayer MS | Paint exterior hollow metal doors and frames | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 15 | EA | \$ 500.00 | \$ 9,000.00 | Building Envelope | ED |
| Strayer MS | Roof replacement | 0 | 1 | 2 | 2 | 2 | 4 | 3 | 3 | 152,000 | SF | \$ 22.00 | \$ 4,012,800.00 | Building Envelope | R |
| Strayer MS | Install storage building 32 x 60 (allowance) | 0 | 1 | 3 | 4 | 1 | 0 | 0 | 3 | 1 | LS | \$ 75,000.00 | \$ 90,000.00 | Site | UN |
| Trumbauersville ES | New ceiling tiles (during lighting upgrade) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 54,647 | SF | \$ 2.00 | \$ 131,152.80 | Interior | СТ |
| Trumbauersville ES | Gym floor refinishing (by QCSD maintenance program) | 1 | 1 | 2 | 3 | 1 | 3 | 4 | 3 | 1 | EA | \$ 15,000.00 | \$ 18,000.00 | Interior | AF |
| Trumbauersville ES | Façade masonry cleaning | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 35,000 | SF | \$ 0.50 | \$ 21,000.00 | Building Envelope | EP |
| Trumbauersville ES | Loading dock retaining wall repairs | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 500 | SF | \$ 35.00 | \$ 21,000.00 | Site | М |
| Trumbauersville ES | Replacement of exterior doors (allowance) | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 6 | EA | \$ 3,500.00 | \$ 25,200.00 | Building Envelope | ED |
| Trumbauersville ES | Loading dock repair / dock bumper | 0 | 1 | 3 | 2 | 2 | 4 | 5 | 3 | 1 | LS | \$ 7,000.00 | \$ 8,400.00 | Site | М |
| Trumbauersville ES | Flat roof replacement (2 areas) | 0 | 1 | 2 | 2 | 2 | 4 | 3 | 3 | 3,500 | SF | \$ 22.00 | \$ 92,400.00 | Building Envelope | R |
| Facilities Building | Mill and overlay all lots and drives | 0 | 0 | 0 | 1 | 0 | 1 | 3 | 1 | 10,000 | SY | \$ 2.00 | \$ 24,000.00 | Site | PA |



13-5 Page 5 of 6

| Building | ltem | SA | EI | PC | DE | EI | AG | LE | PRIORITY | Quantity | Unit (sf, LF, etc.) | Unit Cost | Estimated Cost Including 20% Indirect Costs | Area | Category |
|---------------------|---|----|----|----|----|----|---------|----|----------|----------|------------------------|--------------|---|----------|----------|
| High School | Repave all lots and drives (mill and overlay) | 0 | 0 | 1 | 2 | 0 | 2 | 2 | 1 | 328,750 | SF | \$ 2.00 | \$ 789,000.00 | Interior | PA |
| Sixth Grade Center | Repave all lots and drives (mill and overlay) | 0 | 0 | 1 | 2 | 0 | 2 | 2 | 1 | 117,000 | SF | \$ 2.00 | \$ 280,800.00 | Site | PA |
| Trumbauersville ES | Repave all lots and drives (mill and overlay) | 0 | 0 | 1 | 2 | 0 | 2 | 2 | 1 | 66,600 | SF | \$ 2.00 | \$ 159,840.00 | Site | PA |
| Facilities Building | Roof Replacement (20 year as of 2019) | 0 | 0 | 0 | 1 | 0 | 0 | 1 | 0 | 10,200 | SF | \$ 13.00 | \$ 159,120.00 | Site | PA |
| Quakertown ES | Total Building Renovation | | | | | | | | 0 | 41,172 | SF | \$ 300.00 | \$ 14,821,920.00 | Interior | R |
| | | | | | | | VI, Sin | | | | | Grand Total: | \$ 36,400,534.80 | | |